Oil Field Environmental Incident Summary

Responsible Party: Hess

Well Operator: HESS CORPORATION Well Name: HA-STATE 152-95-1621H-2

Field Name: HAWKEYE Well File #: 23822

Date Incident:1/16/2013Time Incident:21:45Facility ID Number:County:MCKENZIETwp:152Rng:95Sec:16Qtr:

Location Description: Next to spill containment skid near the tank farm berm.

Submitted By: Michael Hyndman Received By:

Contact Person:

3015 16TH ST SW STE 20

MINOT, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site					Reported to NRC:	No
	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels	0	barrels
Brine	0	barrels	0	barrels	0	barrels
Other	100	gallons	100	gallons	100	gallons

Description of Other Released Contaminant:

Baroid Invermul-drilling fluid emulsifier

Inspected: Written Report Received: 2/6/2013 Clean Up Concluded: 1/16/2013

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

95% of the Invermul was recovered from the ground and transferred into the mud system. The remaining 5% was recovered from the ground and mixed with flyash for disposal in to the dry cuttings pit. Upon investigation, it was learned that all other H&P workers were busy in the pump shed so the motorhand took it upon himself to move the loads without utilizing a spotter to ensure the loads were properly picked up. LESSON LEARNED: Always utilize a competent spotter (other worker, truck driver, DSV, EHS Specialist, etc) when moving loads with a forklift.

Wastes Disposal Location: 95% was transferred to the active mud system. Remaining 5% was dried with flyash and placed into the dry cuttings pit.

Agencies Involved:

Updates

Date: 1/17/2013 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location, during drilling operations, according to the report.